

- 1 -

Continental Announces Tire Safety Recall of Approximately 8,500 Tires in U.S., Canada and Mexico

- **Voluntary safety recall program involves Continental ContiProContact tires 225/45 R17 91 H**
- **Loss of air pressure may occur; No reports of accidents**
- **Tires will be replaced at no charge**

Fort Mill, South Carolina, July 16, 2015. Continental today announced a voluntary recall program involving approximately 8,500 passenger vehicle tires. The tires involved in the recall are Continental ContiProContact 225/45 R17 91 H produced between February and May 2015 and sold in the replacement market in the U.S. (4,884 tires), Canada (2,032 tires) and Mexico (1,551 tires).

The tires may experience loss of air pressure. The tires can be identified with the Department of Transportation (DOT) code P5TY PXH6 0815 through P5TY PXH6 1915. Continental has not received any reports of accidents or injuries resulting from this condition.

Continental notified the National Highway Traffic Safety Administration (NHTSA) of the details of the recall on July 15, 2015. The company is in communication with its tire distributors and dealers to identify consumers who purchased affected tires. Owners will be promptly notified and informed about the details of the voluntary safety recall program.

Consumers seeking more information, including instructions for identifying affected tires as well as obtaining replacement tires are asked to visit Continental's website <http://continentaltire.custhelp.com> for more information.

For more information:

Media Contact:

Kathryn Blackwell, Vice President
Communications and Marketing, NAFTA Region
Continental Automotive
One Continental Drive
Auburn Hills, Michigan 48326
Mobile Phone For Media Use Only: 248-462-9114, Fax: 248-393-5227
E-Mail: Kathryn.Blackwell@continental-corporation.com